

Applicant: BATA INDUSTRIALS EUROPE
EUROPAPLEIN 1, 5684 ZC BEST
P.O. BOX 10050 , 5680 DB BEST
THE NETHERLANDS

Date: Jun 27, 2025

Attn: JOEY CHAN

Sample Description:

One (1) pair of submitted samples said to be PU Gumboots in Black.
Standard : --
Size : EUR 42
Ref. No. : Style: ULTRAFLEX Style No.: 802-7001
Date of Sample Received : Jun. 19, 2025/--
Testing Period : Jun. 19, 2025-Jun. 26, 2025
Date Final Information Confirmed/ --/--
Date Payment Received:

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch



Guiliang Dong
Senior Lab Manager



EC/lynnYang

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou 510730
广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房
Tel: +86 020-28209114 Postcode: 510730

www.intertek.com

检验检测专用章

(6)

Splashing Test (Footwear For Limited Contact With Chemicals) (EN 13832-2:2018, 6.2.1.2 & EN 13832-1:2018, 4.2 & Performance Type: Type U)

Test 1	Chemicals Used		Sulfuric Acid 96 %		
Sample	Size	Duration	Assessment	Requirement	Pass/Fail
42	Left	After 10 min	After Testing, No Major Defects Defined In Annex B Of EN 13832-1:2018 Were Detected. No Penetration Inside The Footwear Of Chemical Was Detected. No Spilt Liquid Was Trapped.	*	Pass
		After 60 min	After Testing, No Major Defects Defined In Annex B Of EN 13832-1:2018 Were Detected. No Penetration Inside The Footwear Of Chemical Was Detected. No Spilt Liquid Was Trapped.		
		After 24 Hours	After Testing, No Major Defects Defined In Annex B Of EN 13832-1:2018 Were Detected. No Penetration Inside The Footwear Of Chemical Was Detected. No Spilt Liquid Was Trapped.		
	Right	After 10 min	After Testing, No Major Defects Defined In Annex B Of EN 13832-1:2018 Were Detected. No Penetration Inside The Footwear Of Chemical Was Detected. No Spilt Liquid Was Trapped.	*	Pass
		After 60 min	After Testing, No Major Defects Defined In Annex B Of EN 13832-1:2018 Were Detected. No Penetration Inside The Footwear Of Chemical Was Detected. No Spilt Liquid Was Trapped.		
		After 24 Hours	After Testing, No Major Defects Defined In Annex B Of EN 13832-1:2018 Were Detected. No Penetration Inside The Footwear Of Chemical Was Detected. No Spilt Liquid Was Trapped.		

Remark: * = After Testing, No Major Defects Defined In Annex B Of EN 13832-1:2018 Shall Be Detected After The First (10 min) And The Second (1 h) And The Third (24 h) Assessment. No Penetration Inside The Footwear Of Chemical Shall Be Detected. No Spilt Liquid Shall Be Trapped.

Annex B

- Beginning Of A Pronounced And Deep Cracking Affecting Half The Upper Material Thickness;
- The Upper Shows Areas With Deformations, Chemicals Burns, Fusion Or Bubbles, Or Split Seams;
- Upper/Outsole Separation Of More Than 10 mm Long And 5 mm Wide And/Or Deep;
- The Outsole Shows Cracks More Than 10 mm Long And 3 mm Wide And/Or Deep.



End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

lynnyang

Page 3 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou 510730
广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房
Tel: +86 020 28209114 Postcode: 510730

www.intertek.com

检验检测专用章

INTERTEK SHENZHEN BRANCH (6)