

Number: GZHT91341690

Applicant: BATA INDUSTRIALS EUROPE
EUROPAPLEIN 1, 5684 ZC BEST
P.O. BOX 10050 , 5680 DB BEST
THE NETHERLANDS

Date: Jun 16, 2025

Attn: JOEY CHAN

Sample Description:

One (1) pair of submitted sample said to be PVC gumboot in Black.


Standard : ASTM F2413-24
Size : US 9
Ref. No : WORKMASTER II BLACK
WORKMASTER II WHITE
WORKMASTER II
WADER AMARILLO
Ref. : Toe Cap: Steel toe
Midsole: Steel plate
Upper:PVC
Outsole: PVC
Insock: EVA
Remark: Shipment Test

Date of Sample Received : Jun. 12, 2025
Testing Period : Jun. 12, 2025--Jun. 16, 2025
Date Final Information Confirmed: --

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch



Guiliang Dong
Senior Lab Manager

WQ/lynnyang



Page 1 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
Room 401/501/601/801/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou 510730
广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房
Tel: +86 020-28209114 Postcode: 510730

www.intertek.com

检验检测专用章

INTERTEK SHENZHEN
GUANGZHOU BRANCH
(6)

Electric Hazard Resistant Footwear (EH) (ASTM F2412-24, 9, Conditioned At 22°C And 50% RH For 24 h And Testing Performed At The Same Conditions)

		<u>ASTM F2412-24</u>	<u>Pass/Fail</u>
		<u>Requirement</u>	
Left:	Leakage Current: 0.7 mA	*	Pass
Right:	Leakage Current: 0.8 mA	*	Pass
Left/Right:	-	*	-

Remark: * = No Current Flow Or Leakage Current In Excess of 1.0 mA Under The Application Of 18 000 V At 60 Hz AC For 1 Minute.



End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

lynnnyang

Page 3 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou 510730

广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房

Tel: +86 020 28209114 Postcode: 510730

www.intertek.com

检验检测专用章

INTERTEK SHENZHEN BRANCH (6)